

# VEHICLE INSPECTION REPORT

**RV70DCY**

## Iveco Eurocargo 75-160

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

|           |                      |            |                   |                 |        |
|-----------|----------------------|------------|-------------------|-----------------|--------|
| Location  | Doncaster            | Colour     | WHITE             | Axle Combi      | 4x2    |
| Reg. date | 14/10/2020           | VIN        | ZCFA875BX02700735 | Rear Suspension | Steel  |
| Year      | 2020                 | Body Style | Box Van           | Rear Doors      | Roller |
| Mileage   | 130,242 Km Warranted | MOT Due    | 31/12/2026        | Tail Lift       | Column |
| Fuel Type | Diesel               | Cab Type   | DAY CAB           |                 |        |
| GVW       | 7500kg               | Gearbox    | AUTOMATIC         |                 |        |

\*TAIL LIFT INOP\*

### Tyres





|       |      |      |      |      |
|-------|------|------|------|------|
| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |

## Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim


## Photos







## Condition Check




## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Bumper Front Moulding  
Missing  
Replace



3: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm

4: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



5: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

6: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



7: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

8: Door osf  
Dented  
With Paint Damage



9: Door osf  
 Scratched  
 Over 25mm Thru Paint

10: Door osf  
 Scratched  
 Over 25mm Thru Paint

**Interior**

|                         |    |                             |    |
|-------------------------|----|-----------------------------|----|
| <b>Carpet Condition</b> | OK | <b>Upholstery Condition</b> | OK |
| <b>Seat Condition</b>   | OK | <b>Odour</b>                | -  |
| Engine Runs             | OK | No Excessive Smoking        | OK |
| EML light illuminated   | OK | DPF light illuminated       | OK |
| ABS light illuminated   | OK |                             |    |