



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

S14FGT

DAF XD 450

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	01/06/2023	VIN	XLRTGF5100G463415	Axle Combi	6x2
Year	2023	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	478,870 Km Not Warranted	MOT Due	30/06/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	SLEEPER CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

SLIDING 5TH WHEEL, SURROUND CAMERA SYSTEM


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Digital radio
- Cloth seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Seat Base Cover of
Holed
Over 3mm



2: Screen Front
Chipped
Over 10mm



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front Moulding
Missing
Replace




5: Parking Sensor Front
Broken
Replace




6: Door Mirror Assy nsf
Broken
Replace



7: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



8: Door nsf
Scratched
Over 25mm Thru Paint





9: Wing nsf
Scratched
UpTo 25mm Not Thru Paint

10: Wing Front Arch Extension os
Scratched (Painted)
UpTo 25mm Thru Paint




11: Door Mirror Assy osf
Broken
Replace

12: Door osf
Chipped
Multiple Chips



13: Handle Outer osf
Missing
Replace

14: Wing osf
Cracked
Replace



15: Wing Front Arch Extension os
Missing
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		