

VEHICLE INSPECTION REPORT

PJ20PPU

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 31/07/2020

Year 2020

Mileage 95,486 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9106332P251269

Body Style Panel Van L2

MOT Due 01/08/2025

CAP Clean £11,900.00

CAP Average £10,600.00

CAP Below £8,675.00

Gearbox AUTOMATIC

Axle Combi 4x2

AD-BLUE, SINGLE SIDE DOOR, REAR SENSORS, E/WINDOWS
BEEN ON FULL R&M CONTRACT FROM NEW

Tyres

NSF

NSR


OSF

OSR


Spare

Photos





Condition Check



Damage Photos



1: Wing osf
Rusted
Over 5mm



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Bonnet
Dented
Over 30mm



5: Screen Front
Chipped
UpTo 10mm



6: Wing nsf
Dented
With Paint Damage



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Dented
Over 30% Of Panel




9: Sill ns
Dented
Over 30mm




10: Door Moulding nsr
Missing
Replace



11: Door nsr
Cracked
Replace



12: Door nsr
Dented
With Paint Damage



13: Qtr Panel nsr
Dented
Over 30mm



14: Qtr Panel Trim ns
Broken
Replace



15: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



16: Door nsr
Dented
Over 30mm




17: Door osr
Dented
With Paint Damage



18: Lamp nsr
Broken
Replace



19: Lamp osr
Broken
Replace



20: Qtr Panel osr
Dented
With Paint Damage



21: Sill os
Dented
With Paint Damage



22: General Exterior
Soiled
Light



23: Door osf
Dented
With Paint Damage



24: Door osf
Scratched
Over 25mm Thru Paint



25: Carpets Front
Holed
Over 3mm



26: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK