

VEHICLE INSPECTION REPORT

SV65JZX

Mercedes-Benz Antos 1824

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	31/12/2015	VIN	WDB96300320018416	Gearbox	AUTOMATIC
Year	2015	Body Style	Curtainside	Axle Combi	4x2
Mileage	274,281 Km Not Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/12/2025	Rear Doors	Barn
Colour	BLUE	Cab Type	DAY CAB	Tail Lift	Tuckaway

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Bumper Front
Insecure
Action Required



2: Bumper Front
Insecure
Action Required



3: Headlamp ns
Missing
Replace



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Fog Lamp Surrounds
Scratched (Painted)
Over 25mm Thru Paint



6: C Post ns
Scratched
Over 25mm Thru Paint



7: General Exterior
Soiled
Light



8: General Exterior
Soiled
Light



9: C Post os
Scratched
Over 25mm Thru Paint



10: General Exterior
Soiled
Light



11: Other
N/A
N/A



12: Carpets Front
Holed
Over 3mm



13: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	