

VEHICLE INSPECTION REPORT

SV65JZW

Mercedes-Benz Antos 1824

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/12/2015

VIN WDB96300320018415

Gearbox AUTOMATIC

Year 2015

Body Style Curtainside

Axle Combi 4x2

Mileage 271,056 Km Not Warranted

Service history Yes

Rear Suspension Steel

MOT Due 31/12/2025

Rear Doors Barn

Fuel Type Diesel

Cab Type DAY CAB

Tail Lift Tuckaway

Colour BLUE

SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3


OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Moulding of Wing
Scratched (Painted)
Over 25mm Thru Paint



2: Moulding of Wing
Scratched (Painted)
Over 25mm Thru Paint



3: Bumper Front Grill
Broken
Replace



4: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace



6: General Exterior
Soiled
Light



7: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



8: C Post ns
Scratched
Over 25mm Thru Paint



9: General Exterior
Soiled
Light



10: Door Moulding nsr
Scratched (Painted)
Over 25mm Thru Paint



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door Moulding osr
Scratched (Painted)
Over 25mm Thru Paint



14: General Exterior
Soiled
Light



15: C Post os
Scratched
Over 25mm Thru Paint



16: C Post os
Dented
With Paint Damage



17: General Exterior
Soiled
Light



18: Carpets Front
Holed
Over 3mm



19: Seat Base Cover osf
Torn
Over 3mm



20: Seat Base Cover osf
Holed
Over 3mm



21: Other
N/A
N/A

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	