



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
 Doncaster
 DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BJ68OEO

Mercedes-Benz Citan 109CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	28/09/2018	Colour	WHITE	CAP Average	£3,075.00
Year	2018	VIN	WDF4156032U253248	CAP Below	£2,325.00
Mileage	92,395 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	25/08/2026	Gears	5
GVW	1950kg	CAP Clean	£3,600.00	Axle Combi	4x2


WARNING LIGHTS ON DASH, SIDE LOAD DOOR

Tyres
NSF
NSR
OSF
OSR
Spare

Features

- Cruise control
- Drivers airbag
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim
- Front electric windows

Condition Check



Damage Photos



1: Fascia Trim
Damaged
Replace



2: Dash Warning Lights
Displayed
No Action



3: Bonnet
Chipped
Multiple Chips



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Chipped
Multiple Chips




6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
Hail - Severe



8: Door nsr
Chipped
Multiple Chips





9: Qtr Panel osr
Scratched
Over 25mm Thru Paint

10: Door osf
Chipped
Multiple Chips



11: Moulding osf Wing
Broken
Replace

12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Lamp nsr
Broken
Replace

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		