



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**LO69LNT**

## Ford Ranger 2.0 EcoBlue 170PS

| Inspection      |    | Vehicle |          |
|-----------------|----|---------|----------|
| Serious Damage? | No | VAT     | Plus VAT |
|                 |    | V5      | Present  |

| Details   |                           |            |                   |             |           |
|-----------|---------------------------|------------|-------------------|-------------|-----------|
| Reg. date | 31/12/2019                | Colour     | WHITE             | CAP Average | £7,350.00 |
| Year      | 2019                      | VIN        | 6FPPXXMJ2PKS31198 | CAP Below   | £5,750.00 |
| Mileage   | 93,502 Miles<br>Warranted | Body Style | Pick-up           | Gearbox     | MANUAL    |
| Fuel Type | Diesel                    | MOT Due    | 28/11/2026        | Gears       | 6         |
| GVW       | 3270kg                    | CAP Clean  | £8,500.00         | Axle Combi  | 4x4       |


\*CLICKS ON TURN OVER, ONLY RUNS WITH BOOST PACK, TURBO ISSUES, WARNING LIGHTS ON DASH\*


|       |
|-------|
| Tyres |
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |

## Features


- Bluetooth connection
- Air conditioning
- Passenger airbag
- Cruise control
- Front electric windows
- Central locking
- Auxiliary input socket
- Rear electric windows
- Cloth seat trim
- Digital radio
- Drivers airbag

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Wheel nsf  
Scratched  
Over 50mm



3: Door nsf  
Scratched  
Over 25mm Thru Paint

4: Door nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Dented  
Over 30mm

6: Qtr Panel nsr  
Dented  
With Paint Damage



7: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

8: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



9: Wheel osr  
Scratched  
Over 50mm

10: Door osf  
Dented  
With Paint Damage



11: Wing osf  
Chipped  
Multiple Chips

12: Screen Front  
Chipped  
Up To 10mm



13: Seat Base Cover nsf  
Soiled  
Heavy

**Interior**

**Carpet Condition**  
**Seat Condition**

OK  
Poor

**Upholstery Condition**  
**Odour**

OK  
No

Engine Runs

Fault