

VEHICLE INSPECTION REPORT

RE70LBU

Iveco Eurocargo 75-160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/11/2020

Colour WHITE

Gearbox AUTOMATIC

Year 2020

VIN ZCFA875B902702475

Axle Combi 4x2

Mileage 120,038 Km Warranted

Body Style Box Van

Rear Suspension Steel

Fuel Type Diesel

MOT Due 30/11/2026

Rear Doors Roller

GVW 7500kg

Cab Type DAY CAB

Tail Lift Column

WARNING LIGHTS ON DASH

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door Mirror Assy of
Scuffed (Unpainted)
Over 100mm



2: Bumper Front
Poor Previous Repair
Rippled Up To 30%



3: Bonnet
Chipped
Multiple Chips



4: Panel Front
Scratched
Over 25mm Thru Paint




5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm




6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Qtr Panel osr
Chipped
Multiple Chips





9: Door osf
Chipped
Multiple Chips

10: Door Pad osf
Broken
Replace



11: Seat Base Cover nsf
Torn
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		