

VEHICLE INSPECTION REPORT

YF71VHM

Mercedes-Benz Sprinter 315 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 14/02/2022

Year 2022

Mileage 125,007 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P430177

Body Style Panel Van LWB

MOT Due 17/02/2026

CAP Clean £12,100.00

CAP Average £11,250.00

CAP Below £9,675.00

Gearbox MANUAL

AD-BLUE, SIDE LOAD DOOR, DEADLOCKS (NO KEYS)

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bonnet
Dented
Over 30mm



3: Wing nsf
Dented
Over 30mm



4: Door nsf
Dented
Over 30mm



5: Qtr Panel nsr
Dented
Over 30mm



6: Roof
Dented
Over 30mm



7: Door nsf
Dented
Over 30mm



8: Qtr Panel nsr
Dented
Over 30mm



9: Qtr Panel nsr
Dented
Over 30mm



10: Qtr Panel nsr
Dented
Over 30mm



11: Qtr Panel nsr
Dented
Over 30mm



12: Qtr Panel nsr
Dented
Over 30mm



13: C Post ns
Dented
Over 30mm



14: Badgedecal Rear
Broken
Replace



15: Door nsr
Dented
Over 30mm



16: Door osr
Dented
Over 30mm



17: Qtr Panel osr
Dented
Over 30mm



18: Qtr Panel osr
Dented
Over 30mm




19: Qtr Panel osr
Dented
Over 30mm



20: Qtr Panel osr
Dented
Over 30mm



21: Qtr Panel osr
Dented
Over 30mm



22: Qtr Panel osr
Dented
Over 30mm




23:



24: Qtr Panel osr
Dented
Over 30mm



25: Carpets Front
Holed
Over 3mm



26: Seat Base Cover osf
Holed
Over 3mm



27: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor		Upholstery Condition	OK
Seat Condition	Poor		Odour	No
Engine Runs		OK	No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK