



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MF16XPS

Vauxhall Vivaro 2900 1.6 CDTI BITURBO 120PS ECOFLEX

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	31/03/2016	Colour	SILVER	CAP Clean	£1,900.00
Year	2016	VIN	W0L2F7114GS018360	CAP Average	£1,550.00
Mileage	164,784 Miles Warranted	Body Style	Panel Van L1	CAP Below	£1,100.00
Fuel Type	Diesel	Service history	Yes	Gearbox	MANUAL
GVW	2920kg	MOT Due	30/03/2027	Gears	6

SNAPPED CHASSIS SIDE LOAD DOOR, TOW BAR, E/ MIRRORS, RACKING IN REAR

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag

Photos






Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Dented
Over 30mm

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Door osr
Dented
Over 30mm



11: Door osf
Scratched
Over 25mm Thru Paint

12: Qtr Panel osr
Dented
With Paint Damage



13: Door osf
Chipped
Multiple Chips

14: Screen Front
Cracked
Replace



15: Seat Base Cover of
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		