

VEHICLE INSPECTION REPORT

RE70LBP

Iveco Eurocargo 75-160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/10/2020

Colour WHITE

Axle Combi 4x2

Year 2020

VIN ZCFA875B002702476

Rear Suspension Steel

Mileage 84,731 Km Warranted

Body Style Box Van

Rear Doors Roller

Fuel Type Diesel

Cab Type DAY CAB

Tail Lift Column

GVW 7500kg

Gearbox AUTOMATIC

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint

2: Screen Front
Chipped
UpTo 10mm



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint

10: Door Mirror Assy osf
 Scuffed (Unpainted)
 Over 100mm



11: Wing Front Arch Extension os
 Scuffed (Unpainted)
 UpTo 100mm

12: Wing Front Arch Extension ns
 Scuffed (Unpainted)
 UpTo 100mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK