

VEHICLE INSPECTION REPORT

RV70DEU

Iveco Eurocargo 75-160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 22/10/2020

VIN ZCFA875B702700742

Axle Combi 4x2

Year 2020

Body Style Box Van

Rear Suspension Steel

Mileage 55,931 Km Warranted

MOT Due 30/09/2025

Rear Doors Roller

Fuel Type Diesel

Cab Type DAY CAB

Tail Lift Column

Colour WHITE


Gearbox AUTOMATIC

WARNING LIGHT ON DASH

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



2: Door nsf
Scratched
Over 25mm Thru Paint



3: General Exterior
Soiled
Light

4: General Exterior
Soiled
Light



5: Bumper Rear
Rusted
Over 5mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK