



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

WX14AEP

Ford Transit 350 High Roof Van TDCi 125ps

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	17/03/2014	Colour	WHITE	CAP Average	£1,550.00
Year	2014	VIN	WF0XXXTTFXDD14615	CAP Below	£1,025.00
Mileage	113,474 Miles Warranted	Body Style	Panel Van LWB	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	Expired	Gears	6
GVW	3500kg	CAP Clean	£1,925.00	Axle Combi	4x2

COLLECTED AS NON-RUNNER DUE TO ENGINE FAULT, TAPPING SOUND FROM ENGINE WHEN RUNNING, WARNING LIGHT ON DASH, SIDE LOAD DOOR, TOW BAR, ROOF RACK, HEATED WINDSCREEN, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Fascia Trim
Damaged
Replace



2: Dash Warning Lights
Displayed
No Action



3: Centre Console Front
Holed
Over 3mm

4: Carpets Front
Holed
Over 3mm



5: Screen Front
Chipped
Over 10mm

6: Bonnet
Chipped
Multiple Chips



7: Bumper Front
Insecure
Action Required

8: Bumper Front
Cracked
Over 25mm



9: Wing nsf
Scratched
Over 25mm Thru Paint

10: Door nsf
Dented
2 Or Less Up To 10mm



11: Door nsf
Chipped
Multiple Chips

12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Qtr Panel nsr
Dented
With Paint Damage

14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint

16: Bumper Rear
Scratched
Over 100mm Thru Paint



17: Door nsr
Scratched
UpTo 25mm Thru Paint

18: Door osr
Dented
With Paint Damage



19: Panel Rear
Dented
With Paint Damage

20: Lamp osr
Broken
Replace



21: Bumper Rear
Scratched
Over 100mm Thru Paint

22: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



23: Qtr Panel osr
Rusted
Over 5mm

24: Qtr Panel osr
Scratched
Over 25mm Thru Paint



25: Qtr Panel osr
Rusted
Over 5mm

26: Door osf
Chipped
Multiple Chips



27: Door osf
Scratched
Over 25mm Thru Paint

28: Door Mirror Glass os
Broken
Replace



29: Door Mirror Assy osf
Broken
Replace

30: Bumper Front
Cracked
Over 25mm



31: Roof
Rusted
Over 5mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		