

VEHICLE INSPECTION REPORT

CV16XWG

Ford Transit 350 2.2 TDCI 155PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	15/06/2016	Colour	WHITE	CAP Average	£2,325.00
Year	2016	VIN	WF0XXXTTGXGA15019	CAP Below	£1,675.00
Mileage	168,687 Miles Warranted	Body Style	Panel Van L2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	14/06/2026	Gears	6
GVW	3500kg	CAP Clean	£2,850.00	Axle Combi	4x2

COLLECTED AS NON-RUNNER-ENGINE FAULT, WARNING LIGHT ON DASH 240v SOCKETS, SIDE LOAD DOOR, TOW BAR, ROOF RACK, E/MIRRORS, HEATED WINDSCREEN, SOCKET & USB IN CAB, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF

NSR

OSF

OSR





Spare

Features

- Bluetooth connection
- Drivers airbag
- Park assist camera
- Passenger airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check




Damage Photos



1: Dash Warning Lights
Displayed
No Action

2: Centre Console Front
Holed
Over 3mm



3: Carpets Front
Holed
Over 3mm

4: Seat Base Cover osf
Holed
Over 3mm



5: Screen Front
Chipped
Over 10mm

6: Bonnet
Chipped
Multiple Chips



7: Bumper Front
Scratched
Over 100mm Thru Paint

8: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



9: Wing nsf
Scratched
Over 25mm Thru Paint

10: Door Mirror Assy nsf
Broken
Replace




11: Door Mirror Glass ns
Missing
Replace

12: Door nsf
Scratched
Over 25mm Thru Paint



13: Door Moulding nsf
Scratched (Painted)
UpTo 25mm Thru Paint

14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



16: Qtr Panel nsr
Dented
Over 30mm



17: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



18: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



19: Bumper Rear
Scratched
Over 100mm Thru Paint

20: Door nsr
Dented
With Paint Damage



21: Door osr
Dented
Between 10mm + 30mm



22: Door osr
Scratched
UpTo 25mm Thru Paint




23: Bumper Rear
Scratched
25 to 100mm Thru Paint




24: Qtr Panel osr
Dented
With Paint Damage



25: Qtr Panel osr
Scratched
Over 25mm Thru Paint



26: Qtr Panel osr
Scratched
Over 25mm Thru Paint





27: Qtr Panel osr
Scratched
Over 25mm Thru Paint



28: Door osf
Chipped
Multiple Chips



29: Door Mirror Glass os
Broken
Replace



30: Door Mirror Glass os
Missing
Replace



31: Bonnet
Scratched
Over 25mm Thru Paint

32: Bumper Front
Scratched
Over 100mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault		
ABS light illuminated	Fault		