



COMMERCIAL VEHICLE AUCTIONS LTD  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**WV74LVB**

## Maxus Deliver 9 2.0 D20 150PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	12/09/2024	Colour	WHITE	CAP Average	£10,450.00
Year	2024	VIN	LSH14J7C4PA183132	CAP Below	£9,200.00
Mileage	60,545 Miles Not Warranted	Body Style	Panel Van LWB	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	11/09/2027	Gears	6
GVW	3500kg	CAP Clean	£11,050.00		

AD-BLUE, SIDE LOADING DOOR

### Tyres

NSF

NSR

OSF

OSR






Spare

## Features


- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Dented  
With Paint Damage



2: Wing Front Arch Extension os  
Missing  
Replace



3: Bumper Front  
Insecure  
Action Required

4: Bonnet  
Dented  
With Paint Damage



5: Bumper Front  
Scratched  
25 to 100mm Thru Paint

6: Bumper Front  
Scratched  
25 to 100mm Thru Paint



7: Bumper Front  
Scratched  
25 to 100mm Thru Paint

8: Bumper Front  
Insecure  
Action Required



9: Wing Front Arch Extension ns  
Missing  
Replace

10: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



11: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm

12: Flasher Side Repeater ns  
Broken  
Replace



13: Door nsf  
Scratched  
Over 25mm Not Thru Paint

14: Door nsr  
Dented  
With Paint Damage



15: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

16: Sill ns  
Dented  
With Paint Damage



17: Sill ns  
Dented  
With Paint Damage

18: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Up To 100mm



19: Door nsr  
Scratched  
Over 25mm Not Thru Paint

20: Badgedecal Rear  
Broken  
Replace



21: Door osr  
Dented  
With Paint Damage

22: Door osr  
Hole  
Over 10mm



23: Roof  
Dented  
With Paint Damage

24: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



25: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm

26: Flasher Side Repeater os  
Broken  
Replace



27: Door osf  
 Scratched  
 Over 25mm Thru Paint

28: Seat Base Cover osf  
 Holed  
 Over 3mm



29: Carpets Front  
 Holed  
 Over 3mm

**Interior**

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK