

VEHICLE INSPECTION REPORT

BT68LVU

Iveco Eurocargo 120-210

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 02/01/2019

VIN ZCFAG1EF902687348

Cab Type SLEEPER CAB

Year 2019

Body Style Curtainside

Gearbox AUTOMATIC

Mileage 211,233 Km Warranted

Service history Yes

Axle Combi 4x2

Fuel Type Diesel

Service documents Electronic / Online

Rear Suspension Steel

Colour WHITE

MOT Due 28/02/2026

Tail Lift Cantilever

WARNING LIGHTS ON DASH, OIL LEAK, STARTER ISSUES

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Bumper Front
Poor Previous Repair
Poor Paint



2: Screen Front
Chipped
UpTo 10mm



3: Bumper Front
Poor Previous Repair
Poor Paint



4: Bumper Front
Poor Previous Repair
Poor Paint



5: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



6: General Exterior
Soiled
Light



7: Door Mirror Assy nsf
Missing
Replace



8: General Exterior
Soiled
Light



9: Fascia Panel
Missing
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		Fault	
ABS light illuminated		OK		Service indicator light illuminated		OK	