

VEHICLE INSPECTION REPORT

BN14WVA

Iveco Eurocargo 75E16S

| Inspection | | venicie | | | |
|-----------------|----------------------|------------|-------------------|-----------------|------------|
| Serious Damage? | No | VAT | Plus VAT | | |
| | | V5 | To Follow | - | |
| Details | | | | | |
| Reg. date | 06/03/2014 | VIN | ZCFA675B502623049 | Axle Combi | 4x2 |
| Year | 2014 | Body Style | Box Van | Rear Suspension | Steel |
| Mileage | 682,676 Km Warranted | MOT Due | 28/02/2026 | Tail Lift | Cantilever |
| Fuel Type | Diesel | Cab Type | DAY CAB | - | |
| Colour | RED | Gearbox | MANUAL | - | |

COLLECTED AS NON RUNNER - AIR TANKS, TAIL LIFT, BRAKE PIPE ISSUES *CLUTCH NOISE*

Tyres

| NSF | NSI1 | NSI2 | NSI3 | NSI4 | |
|-------|------|------|------|------|--|
| OSF | OSI1 | OSI2 | OSI3 | OSI4 | |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 | |
| | OS01 | OSO2 | OSO3 | OSO4 | |

Photos























Condition Check



Damage Photos



1: Screen Front Scratched Over 30mm



2: Bumper Front Scratched Over 100mm Thru Paint



3: Qtr Panel nsr Scratched Over 25mm Thru Paint



4: Qtr Panel Trim ns Scuffed Over 25mm



5: Tailgate Rusted Holed



6: Door osf Chipped Multiple Chips



7: Door Pad osf Broken Replace



8: Seat Base Cover nsf Torn Over 3mm



9: Screen Front Chipped Over 10mm

Interior

| Carpet Condition Seat Condition | OK Poor | | Upholstery Condition Odour | Poor - | |
|---------------------------------|------------|----|-------------------------------|-----------|----|
| Engine Runs | | OK | No Excessive Smoking | | OK |
| EML light illuminated | | OK | DPF light illuminated | | ОК |
| ABS light illuminated | | OK | | | |