

# VEHICLE INSPECTION REPORT

**DA69GOJ**

## Isuzu N75 190

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 19/11/2019

VIN JAANPR75HJ7104178

Gearbox AUTOMATIC

Year 2019

Body Style Flatbed

Axle Combi 4x2

Mileage 266,778 Km Warranted

Service history Yes

Rear Suspension Steel

Fuel Type Diesel

MOT Due 31/01/2026

Colour WHITE

Cab Type DAY CAB

\*WARNING LIGHT ON DASH\*

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Bluetooth connection
- Drivers airbag
- Park assist camera
- Passenger airbag
- Radio/CD
- Cloth seat trim
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Door osf  
Dented  
Over 30mm



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Headlamp os  
Broken  
Replace



4: Bonnet  
Dented  
Over 30mm



5: Screen Front  
Cracked  
Replace



6: Bumper Front  
Scratched  
Over 100mm Thru Paint



7: Seat Base Cover osf  
Soiled  
Heavy

## Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Poor	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		