

# VEHICLE INSPECTION REPORT

**RV70DJD**

## Iveco Eurocargo 75-160

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 09/11/2020

VIN ZCFA875B502700822

Axle Combi 4x2

Year 2020

Body Style Box Van

Rear Suspension Steel

Mileage 68,250 Km Warranted

MOT Due 31/03/2026

Rear Doors Roller

Fuel Type Diesel

Cab Type DAY CAB

Tail Lift Column

Colour WHITE

Gearbox AUTOMATIC

\*WARNING LIGHT ON DASH\*

### Tyres

NSF NSI1 NSI2 NSI3 NSI4


OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4


### Photos







## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



3: Screen Front  
Chipped  
UpTo 10mm



4: Bonnet  
Chipped  
Multiple Chips



5: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



6: General Exterior  
Soiled  
Light



7: Door Moulding nsf  
Scratched (Painted)  
Over 25mm Thru Paint



8: General Exterior  
Soiled  
Light



9: Bumper Rear  
Rusted  
Over 5mm



10: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



11: General Exterior  
Soiled  
Light



12: Carpets Front  
Holed  
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK