

# VEHICLE INSPECTION REPORT

**DG18CUU**

## Isuzu N75 190

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	15/03/2018	VIN	JAANPR75MH7100544	Rear Suspension	Steel
Year	2018	Body Style	Curtainside	Rear Doors	Roller
Mileage	330,114 Km Warranted	MOT Due	31/01/2026	Tail Lift	Column
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	RED/WHITE	Axle Combi	4x2		

SURROUND CAMERA SYSTEM, BEEN ON FULL R&M CONTRACT FROM NEW

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


### Photos







## Condition Check



## Damage Photos



1: Door Mirror Assy of  
Scuffed (Unpainted)  
Over 100mm



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Bonnet  
Scratched  
Over 25mm Thru Paint



4: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm



5: Door osf  
Scratched  
Over 25mm Thru Paint



6: Seat Base Cover osf  
Holed  
Over 3mm



7: Seat Base Cover osf  
Burn  
Over 3mm

## Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	