

VEHICLE INSPECTION REPORT

SV70NWW

Scania R 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	17/09/2020	VIN	YS2R6X20005595346	Cab Type	NORMAL SLEEPER CAB
Year	2020	Body Style	Tractor Unit	Gearbox	AUTOMATIC
Mileage	494,554 Km Warranted	MOT Due	Expired	Axle Combi	6x2
Fuel Type	Diesel	CAP Clean	£29,800.00	Steering Combi	Mid-Lift
GVW	44000kg	CAP Average	£28,050.00	Rear Suspension	Air
Colour	WHITE	CAP Below	£25,200.00		

WARNING LIGHTS ON DASH, SUNROOF INOP SLIDING 5TH WHEEL, SURROUND CAMERA SYSTEM, FRIDGE, TWIN LINE PTO HYDRAULICS


Tyres



NSF	OK	NSI1	NSI2	NSI3	NSI4
OSF	OK	OSI1	OSI2	OSI3	OSI4
Spare		NSO1	NSO2	NSO3	NSO4
		OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Auxiliary input socket
- Air conditioning
- Heated front seat
- Mobile phone App interface
- Front electric windows
- Navigation system
- USB/iPod interface
- Central locking
- Park assist camera
- Manual sunroof
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Dented
Over 2 UpTo 10mm

4: Bonnet
Scratched
Over 25mm Thru Paint



5: A Post os
Dented
Between 10mm + 30mm

6: Door osf
Scratched
Over 25mm Not Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint

8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint

10: Bonnet
Chipped
1 To 5



11: Bumper Front
Dented
Over 30mm

12: Bumper Front
Hole
Over 25mm



13: B Post ns
Scratched
Over 25mm Thru Paint

14: Other
N/A
N/A



15: Other
N/A
N/A

16: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		No Excessive Smoking	OK	
Parking Brake	OK				
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Roof / sunroof	Fault		Radio	OK	
Windows	OK		Steering	OK	