

VEHICLE INSPECTION REPORT

FV22HYH

Ford Transit 2.0 ECOBLUE 130PS

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	16/05/2022	Colour	SILVER	CAP Average	£11,650.00
Year	2022	VIN	WF0EXXTTRENY38598	CAP Below	£10,000.00
Mileage	65,895 Miles Not Warranted	Body Style	Panel Van L4	Gearbox	MANUAL
		CAP Clean	£12,550.00	Gears	6
Fuel Type	Diesel				

^{*}WARNING LIGHT ON DASH* AD BLUE, SINGLE SIDE DOOR, E/MIRRORS

Tyres NSF

NSR

OSF

OSR

Spare

Features

Front parking sensor

· Rear parking sensor

· Air conditioning

• Front electric windows

Photos
















Condition Check



Damage Photos



1: Wing osf Scratched Over 25mm Thru Paint



2: Screen Front Chipped UpTo 10mm



3: Panel Front Scratched Over 25mm Thru Paint



4: Fog Lamp Surround os Missing Replace



5: Number Plate Front Missing Replace



6: Door Mirror Assy nsf Broken Replace



7: Fuel Flap Missing Replace



8: Door nsr Dented With Paint Damage



9: Door nsr Hole Over 10mm



10: Door nsr Dented 2 Or Less UpTo 10mm



11: Bumper Rear Cracked Over 25mm



12: Door nsr Dented With Paint Damage



13: Door nsr Dented Over 30mm



14: Other N/A N/A



15: Bumper Rear Cracked Over 25mm



16: Bumper RearScratchedOver 25mm Not Thru Paint



17: Qtr Panel nsr Missing Replace



18: Qtr Panel osr Scratched Over 25mm Thru Paint



19: Qtr Panel osr Dented With Paint Damage



20: Qtr Panel nsr Dented With Paint Damage



21: Qtr Panel osr Scratched Over 25mm Not Thru Paint



22: Door osf Dented With Paint Damage



23: Door Mirror Assy osf Scuffed (Unpainted) Over 100mm



24: Door Mirror Glass os Missing Replace



25: Other N/A N/A



26: Seat Base Cover nsf Holed Over 3mm

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average No	
Engine Runs		OK	Gearbox 1st and Revers	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Parking Brake		OK	Gearbox Static Gear Sel	ection (engine running)	OK
			No Excessive Smoking		OK
EML light illuminated		ОК	Oil warning light illumina	ted	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		Fault	Service indicator light illu	ıminated	OK