

VEHICLE INSPECTION REPORT

HX73YSL

Mercedes-Benz Atego 816

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	23/01/2024	Colour	WHITE	MOT Due	31/01/2027
Year	2024	VIN	W1T96700820678885	Cab Type	DAY CAB
Mileage	19,010 Km Warranted	Body Style	Flatbed & Crane	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service history	Yes	Axle Combi	4x2
GVW	7490kg	Service documents	Printout	Rear Suspension	Steel

WARNING LIGHTS ON DASH HIAB HIDUO 062 B-2 REMOTE CRANE (YEAR 2023)

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Digital radio
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Auxiliary input socket
- Cloth seat trim


Photos







Condition Check




Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Seat Base Cover osf
Soiled
Heavy

4: Dash Warning Lights
Displayed
No Action



5: Door Pad osf
Soiled
Heavy

Interior

Carpet Condition		OK	Upholstery Condition		Poor
Seat Condition		Poor	Odour		-
Engine Runs	OK		No Excessive Smoking	OK	
EML light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	Fault	