

VEHICLE INSPECTION REPORT

PE70UNH

Fiat Ducato 35 MAXI 2.3 MULTIJET 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 09/10/2020

Year 2020

Mileage 62,904 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA25000002P07002

Body Style Panel Van LWB

MOT Due 13/11/2025

CAP Clean £8,875.00

CAP Average £7,900.00

CAP Below £6,475.00

Gearbox MANUAL

Gears 6

SINGLE SIDE DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Bumper Front
Cracked
Over 25mm



5: Bumper Front
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Wing nsf
Chipped
1 To 5



8: Door nsf
Chipped
Multiple Chips



9: Door nsr
Chipped
Multiple Chips



10: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel Trim ns
Scuffed
Over 25mm



12: Qtr Panel Trim ns
Scuffed
Over 25mm



13: Door nsr
Chipped
Multiple Chips



14: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



15: General Exterior
Soiled
Light



16: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average	Odour	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK