

VEHICLE INSPECTION REPORT

PA19DFL

Mercedes-Benz Sprinter 316 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 27/08/2019

Year 2019

Mileage 129,752 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN WDB9076332P096633

Body Style Panel Van L1

MOT Due Expired

CAP Clean £8,775.00

CAP Average £7,575.00

CAP Below £5,925.00

Gearbox MANUAL

Gears 4

Axle Combi 4x2

BATTERY & ALTERNATOR ISSUES, OUTSTANDING RECALL, WARNING LIGHTS ON DASH AD BLUE, SIDE LOAD DOOR, TOW BAR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Mobile phone App interface
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Digital radio
- Drivers airbag

Photos






Condition Check



Damage Photos



1: Door osf
Dented
Over 30% Of Panel

2: Wing osf
Missing
Replace



3: Wing osf
Rusted
UpTo 5mm

4: Door osf
Hole
UpTo 10mm



5: Qtr Panel osr
Dented
With Paint Damage

6: Qtr Panel osr
Dented
Over 30mm



7: Qtr Panel Trim os
Missing
Replace

8: Qtr Panel Trim os
Scuffed
Over 25mm



9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

10: Door nsr
Dented
Over 30mm



11: Door nsr
Dented
Over 30mm

12: Wing nsf
Missing
Replace



13: Wing nsf
Dented
Over 30mm

14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bumper Front
Missing
Replace

16: Bumper Front Moulding
Broken
Replace



17: Screen Front
Chipped
Over 10mm

18: Seat Base Cover osf
Torn
Over 3mm



19: Seat Base Cover osf
Missing
Replace

20: Seat Base Cover osf
Soiled
Heavy



21: General Interior
Soiled
Light

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK			
EML light illuminated		Fault			
ABS light illuminated		OK			