

VEHICLE INSPECTION REPORT

NX23HHY

Fiat Doblo Maxi 1.5 BLUEHDI 1000kg PRIMO 100PS

Non Runner
Inspection

Serious Damage?		Vehicle	
No		VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	26/07/2023	Colour	WHITE	CAP Below	£7,475.00
Year	2023	VIN	VYFEFYHT2PJ672353	Gearbox	MANUAL
Mileage	Not Showing	Body Style	Panel Van L2	Gears	6
Fuel Type	DIESEL	CAP Clean	£9,400.00		
GVW	2400kg	CAP Average	£8,700.00		

NON RUNNER - DOES NOT TURN OVER TWIN SIDE LOAD DOOR, E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF


OSR



Spare

Features

- Bluetooth connection
- Auxiliary input socket
- Drivers airbag
- Cruise control
- Digital radio
- Passenger airbag
- Navigation system
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint

2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Fogdriving Lamp nsf
Broken
Replace

4: Panel Front
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Dented
Over 30mm (Steel)

6: Sill ns
Dented
With Paint Damage



7: Sill ns
Dented
Over 30mm

8: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



9: Qtr Panel nsr
Dented
Over 30mm

10: Qtr Panel nsr
Scratched
UpTo 25mm Not Thru Paint



11: Wheel nsr
Dented
Over 30mm (Steel)

12: Bumper Rear
Cracked
Over 25mm



13: Door nsr
Dented
With Paint Damage

14: Door osr
Dented
With Paint Damage



15: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint

16: Qtr Panel osr
Dented
Over 30% Of Panel



17: Wheel osr
Dented
Over 30mm (Steel)

18: Door osr
Dented
Over 30mm



19: Sill os
Dented
With Paint Damage

20: Qtr Panel osr
Dented
With Paint Damage



21: Qtr Panel osf
Dented
Over 30mm

22: Door osf
Dented
Over 30mm




23: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint

24: Wheel osf
Dented
Over 30mm (Steel)



25: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint

26: Wing osf
Dented
Over 30mm



27: Seat Base Cover nsf
Soiled
Heavy

28: Fascia Panel
Missing
Replace

Interior

Carpet Condition OK
Seat Condition Poor

Upholstery Condition Poor
Odour No

Engine Runs Fault