

VEHICLE INSPECTION REPORT



Daf LF 45.140

| Inspection | Vehicle | | |
|--------------------|---------|----------|--|
| Serious Damage? No | VAT | Plus VAT | |
| | V5 | Present | |

| Details | | | | | |
|-----------|----------------------|-------------------|-------------------|-----------------|------------|
| Reg. date | 28/11/2013 | VIN | XLRAE45FF0L433122 | Cab Type | DAY CAB |
| Year | 2013 | Body Style | Box Van | Gearbox | MANUAL |
| Mileage | 982,628 Km Warranted | Service history | Yes | Axle Combi | 4x2 |
| Fuel Type | Diesel | Service documents | Printout | Rear Suspension | Steel |
| Colour | RED | MOT Due | 31/07/2025 | Tail Lift | Cantilever |

COLLECTED AS NON RUNNER - CORROSION, GEARBOX & CLUTCH ISSUES

| Tyres | | | | |
|-------|------|------|------|------|
| NSF | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
| | OS01 | OSO2 | OSO3 | OSO4 |

Features

| Cruise control | Radio/CD | Front electric windows | Cloth seat trim |
|------------------------------------|----------|--|-------------------------------------|
|------------------------------------|----------|--|-------------------------------------|

Photos




































Condition Check



Damage Photos





1: Bonnet Chipped Multiple Chips

2: Bumper Front Grill Broken Replace





4: Door Mirror Assy nsf Broken Replace



5: Qtr Panel nsr Scratched Over 25mm Not Thru Paint

Cracked



6: Qtr Panel osr Scratched Over 25mm Thru Paint



7: Door osf Scratched Over 25mm Thru Paint

Interior



8: Door Pad osf Soiled Heavy

| Carpet Condition Seat Condition | OK OK | | Upholstery Condition Odour | Poor - | |
|------------------------------------|----------|----|-------------------------------|-----------|----|
| Engine Runs | | ОК | No Excessive Smoking | | OK |
| EML light illuminated | | OK | DPF light illuminated | | OK |
| ABS light illuminated | | OK | | | |