

VEHICLE INSPECTION REPORT

LL15UVK

Mercedes-Benz Econic 2630

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/07/2015

Colour WHITE

Gearbox AUTOMATIC

Year 2015

VIN WDB9560632V239216

Axle Combi 6x4

Mileage 317,222 Km Warranted

Body Style Refuse Collector

Rear Suspension Air

Fuel Type DIESEL

MOT Due 31/12/2026

GVW 26000kg

Cab Type CREW CAB

COLLECTED AS NON-RUNNER - KEEPS CUTTING OUT *INPUT ERROR ON MOT, WARNING LIGHTS ON DASH* FAUN VARIOPRESS, SINGLE BIN LIFT

Tyres

NSF NSI1 NSI2 NSI3 NSI4




OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4


Photos







Condition Check



Damage Photos



1: Bumper Front
Cracked
UpTo 25mm

2: Wing osf
Scratched
Over 25mm Not Thru Paint



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Flasher Side Repeater ns
Missing
Replace

6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

8: Flasher Side Repeater os
Missing
Replace



9: Seat Base Cover osf
Holed
Over 3mm

10: Centre Console Front
Broken
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	Fault		