

# VEHICLE INSPECTION REPORT

**PG66UES**

## Daf CF 440

**Non Runner  
Inspection**

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | Present  |

### Details

|           |                           |            |                   |                 |           |
|-----------|---------------------------|------------|-------------------|-----------------|-----------|
| Reg. date | 27/02/2017                | Colour     | RED               | Gearbox         | AUTOMATIC |
| Year      | 2017                      | VIN        | XLRTGM4100G147933 | Axle Combi      | 6x2       |
| Mileage   | 1,302,148 Km<br>Warranted | Body Style | Tractor Unit      | Steering Combi  | Mid-Lift  |
| Fuel Type | DIESEL                    | MOT Due    | 28/02/2027        | Rear Suspension | Air       |
| GVW       | 44000kg                   | Cab Type   | SLEEPER CAB       |                 |           |

**\*NON RUNNER-REQUIRES NEW ENGINE\*\*WARNING LIGHTS ON DASH\* SURROUND CAMERA SYSTEM**

### Tyres





|       |      |      |      |      |
|-------|------|------|------|------|
| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |

## Features

- Cruise control
- Radio/CD
- Manual sunroof
- Air conditioning
- Front electric windows
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Bumper Front Grill  
Broken  
Replace



3: Bumper Front  
Rusted  
Over 5mm

4: Bumper Front  
Rusted  
Over 5mm



5: Wing nsf  
Cracked  
Replace

6: Door nsf  
Poor Previous Repair  
Poor Colour



7: Door nsf  
Scratched  
Over 25mm Thru Paint

8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



10: Door osf  
Scratched  
Over 25mm Thru Paint



11: Door osf  
Scratched  
Over 25mm Thru Paint

12: Moulding osf Wing  
Scratched (Painted)  
Over 25mm Thru Paint



13: B Post os  
Rusted  
Over 5mm

14: Carpets Front  
Holed  
Over 3mm



15: Seat Base Cover osf  
Holed  
Over 3mm

16: Switches And Controls  
Missing  
Replace

Interior

|                  |         |                      |         |
|------------------|---------|----------------------|---------|
| Carpet Condition | Average | Upholstery Condition | Average |
| Seat Condition   | Average | Odour                | -       |
| Engine Runs      |         | Fault                |         |