

VEHICLE INSPECTION REPORT

NL72HZX

Renault Master LM35 2.3 DCI 135PS BUSINESS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	30/09/2022	Colour	WHITE	CAP Average	£11,700.00
Year	2022	VIN	VF1MA000168873828	CAP Below	£9,850.00
Mileage	32,353 Miles Not Warranted	Body Style	Panel Van LWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	29/09/2026	Gears	6
GVW	3500kg	CAP Clean	£12,900.00		

WARNING LIGHTS ON DASH AD-BLUE, SIDE LOAD DOOR, SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR




Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

2: Screen Front
Cracked
Replace



3: Bonnet
Chipped
Multiple Chips

4: Bumper Front
Dented
Over 30mm





5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Wing nsf
Dented
With Paint Damage



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

8: Door nsf
Scratched
Over 25mm Not Thru Paint





9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




11: Qtr Panel nsr
Dented
Between 10mm + 30mm

12: Qtr Panel nsr
Hole
Over 10mm



13: Lamp osr
Broken
Replace

14: Handle Outer osr
Broken
Replace



15: Door osr
Dented
With Paint Damage



16: Qtr Panel nsr
Dented
With Paint Damage



17: Qtr Panel osr
Hole
Over 10mm

18: Seat Base Cover osf
Burn
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault