

VEHICLE INSPECTION REPORT

NL72JCU

Renault Master LM35 2.3 DCI 135PS BUSINESS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	30/09/2022	Colour	WHITE	CAP Average	£11,800.00
Year	2022	VIN	VF1MA000268873840	CAP Below	£9,900.00
Mileage	31,276 Miles Not Warranted	Body Style	Panel Van LWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	03/10/2026	Gears	6
GVW	3500kg	CAP Clean	£12,950.00		

AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Rear parking sensor
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Dented
Between 10mm + 30mm

2: Screen Front
Chipped
Over 10mm



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Bonnet
Dented
With Paint Damage

6: Roof
Rusted
Over 5mm



7: Door Mirror Assy nsf
Broken
Replace

8: Door nsr
Dented
With Paint Damage



9: Door nsf
Scratched
Over 25mm Not Thru Paint

10: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm





11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

12: Door osr
Scratched
Over 25mm Thru Paint



13: Lamp osr
Broken
Replace

14: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm





15: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

16: Seat Base Cover osf
Holed
Over 3mm



17: Door Pad osf
Broken
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK