

VEHICLE INSPECTION REPORT

NK15ZVG

Scania P250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 24/04/2015

VIN YS2P4X20005381749

Axle Combi 4x2

Year 2015

Body Style Fridge Box

Rear Suspension Steel

Mileage 828,787 Km Warranted

MOT Due 31/03/2026

Rear Doors Roller

Fuel Type Diesel

Cab Type DAY CAB

Colour WHITE

Gearbox AUTOMATIC

THERMOKING T-1000R UNIT

Tyres

NSF NSI1 NSI2 NSI3 NSI4



OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Photos





Condition Check



Damage Photos



1: Moulding onf Wing
Scratched (Painted)
Over 25mm Thru Paint



2: General Exterior
Soiled
Light




3: Door Mirror Assy nsf
Broken
Replace



4: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



5: Bumper Front
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel nsr
Hole
Over 10mm



7: Qtr Panel nsr
Hole
Over 10mm



8: General Exterior
Soiled
Light



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint

10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: In Car Entertainment
Missing
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	