

VEHICLE INSPECTION REPORT

AY18JVP

Mercedes-Benz Actros 1840

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	14/06/2018	Colour	WHITE	Gearbox	AUTOMATIC
Year	2018	VIN	WDB96300320244011	Axle Combi	4x2
Mileage	833,358 Km Not Showing	Body Style	Chassis Cab	Rear Suspension	Air
Fuel Type	Diesel	MOT Due	31/07/2026		
GVW	18000kg	Cab Type	STREAMSPACE CAB (2.3M, 170MM)		

TWIST LOCKS (4) C/W DONBUR DRAWBAR TRAILER, ID: C480070, BPW DRUM AXLES, YEAR: 2018, VIN: SEPDT18KJL068176, 6.4M LENGTH, MOT: 31/08/2026, TWIST LOCKS (4)

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4



Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Screen Front
Chipped
UpTo 10mm



2: Bonnet
Cracked
Replace



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Door Mirror Assy nsf
Broken
Replace



5: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

6: Bumper Rear
Dented
Between 10mm + 30mm



7: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm

8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	