

VEHICLE INSPECTION REPORT

NL72JCV

Renault Master LM35 2.3 DCI 135PS BUSINESS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/09/2022

Year 2022

Mileage 37,797 Miles Not Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN VF1MA000168873831

Body Style Panel Van LWB

MOT Due 29/09/2026

CAP Clean £12,450.00

CAP Average £11,350.00

CAP Below £9,500.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR





Spare

Features


- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm




2: Screen Front
Chipped
UpTo 10mm



3: Bonnet
Chipped
Multiple Chips

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door Mirror Assy nsf
Broken
Replace



7: Door nsr
Dented
Between 10mm + 30mm

8: Qtr Panel Moulding ns
Broken
Replace



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Door nsr
Dented
With Paint Damage





11: Door osf
Scratched
Over 25mm Not Thru Paint

12: Lamp osr
Broken
Replace



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

14: Qtr Panel osr
Dented
With Paint Damage



15: Qtr Panel osr
Dented
Between 10mm + 30mm



16: Wing osf
Scratched
Over 25mm Not Thru Paint



17: Seat Base Cover osf
Burn
Over 3mm

18: Seat Base Cover nsf
Burn
Over 3mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK