

VEHICLE INSPECTION REPORT

FJ68XHZ

Mercedes-Benz Actros 2530

Non Runner
Inspection

Serious Damage?		Vehicle	
No		VAT	Plus VAT
		V5	Present

Details

Reg. date	24/12/2018	Colour	WHITE	Gearbox	AUTOMATIC
Year	2018	VIN	WDB96302020291739	Axle Combi	6x2
Mileage	495,136 Km Not Warranted	Body Style	Curtainside	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	30/09/2026	Rear Doors	Barn
GVW	26000kg	Cab Type	SLEEPER CAB	Tail Lift	Tuckaway

NON-RUNNER - TURNS OVER DOES NOT START REAR LIFT

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Fog Lamp Surround os
Scratched (Painted)
UpTo 25mm Thru Paint



2: Grille Front
Scratched (Painted)
Over 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Wing osf
Scratched
Over 25mm Not Thru Paint



5: Screen Front
Cracked
Replace



6: Wing nsf
Scratched
UpTo 25mm Thru Paint



7: Door Mirror Assy nsf
Broken
Replace



8: Door nsf
Scratched
Over 25mm Thru Paint





9: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint

10: Door Mirror Assy osf
Broken
Replace



11: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Not Thru Paint

12: Door osf
Scratched
Over 25mm Not Thru Paint



13: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs		Fault	