

# VEHICLE INSPECTION REPORT

**KT15YZN**

## Mercedes-Benz Sprinter 313 CDI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

### Details

Reg. date	25/06/2015	Colour	WHITE	CAP Clean	£4,725.00
Year	2015	VIN	WDB9066332P162449	CAP Average	£3,875.00
Mileage	77,202 Miles Not Warranted	Body Style	Panel Van MWB	CAP Below	£2,775.00
Fuel Type	Diesel	MOT Due	20/06/2025	Gearbox	MANUAL

SINGLE SIDE DOOR

### Tyres

NSF

NSR

OSF

OSR


Spare

## Features

- Front electric windows


## Photos







## Condition Check



## Damage Photos




1: Screen Front  
Chipped  
UpTo 10mm



2: Bonnet  
Rusted  
Over 5mm



3: Grille Front  
Broken  
Replace



4: B Post ns  
Rusted  
Over 5mm



5: Sill ns  
Dented  
With Paint Damage



6: Qtr Panel nsr  
Rusted  
Over 5mm



7: Qtr Panel nsr  
Dented  
With Paint Damage



8: Door osr  
Dented  
With Paint Damage





9: Qtr Panel osr  
Rusted  
UpTo 5mm



10: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



11: Carpets Front  
Holed  
Over 3mm



12: Seat Base Cover osf  
Torn  
Over 3mm



13: Other  
N/A  
N/A



14: Sill os  
Rusted  
Over 5mm

## Interior

<b>Carpet Condition</b>	<b>Average</b>	<b>Upholstery Condition</b>	<b>Average</b>
<b>Seat Condition</b>	<b>Average</b>	<b>Odour</b>	<b>No</b>
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK