

VEHICLE INSPECTION REPORT

BF19WAU

Volvo FMX 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 01/03/2019

Year 2019

Mileage 537,451 Km Not Warranted

Fuel Type DIESEL

GVW 32000kg

Colour RED

VIN YV2XZX0G9KB892823

Body Style Tipper

MOT Due 31/01/2027

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

BOWELD BODY, EDBRO TIPPER GEAR, AIR OP. BACK DOOR, SHEETING SYSTEM, SURROUND CAMERA SYSTEM

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bonnet
Chipped
Multiple Chips




3: Screen Front
Chipped
Over 10mm

4: Fog Lamp Surround ns
Broken
Replace



5: Bumper Front
Scratched
Over 100mm Thru Paint

6: Door Mirror Glass ns
Broken
Replace



7: Door nsf
Scratched
Over 25mm Thru Paint

8: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Bumper Rear
Rusted
Over 5mm



11: Door nsr
Scratched
Over 25mm Thru Paint

12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Dented
With Paint Damage

14: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



15: Door Mirror Glass os
Broken
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	