

VEHICLE INSPECTION REPORT

NU18GKJ

Man TGX 18.420

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 24/04/2018

Colour BLUE

Gearbox AUTOMATIC

Year 2018

VIN WMA06XZZ0JM787506

Axle Combi 4x2

Mileage 675,572 Km Warranted

Body Style Tractor Unit

Rear Suspension Air

Fuel Type DIESEL

MOT Due 31/07/2027

GVW 28000kg

Cab Type XLX CAB

SLIDING 5TH WHEEL

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Bonnet
Chipped
Multiple Chips



5: Panel Front
Scratched
Over 25mm Thru Paint

6: Door nsf
Dented
Over 30mm




7: Qtr Panel nsr
Dented
Over 30mm

8: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm



9: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

10: Qtr Panel Moulding os
Broken
Replace



11: Qtr Panel Trim os
Broken
Replace

12: Qtr Panel osr
Dented
Over 30mm



13: Door osf
Dented
With Paint Damage

14: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



15: Door Pad osf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		