

VEHICLE INSPECTION REPORT

DX70TFK

Daf LF 180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	28/10/2020	Colour	WHITE	Gearbox	MANUAL
Year	2020	VIN	XLRAEL1500L495034	Axle Combi	4x2
Mileage	103,592 Km Warranted	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	30/11/2026	Rear Doors	Roller
GVW	7500kg	Cab Type	DAY CAB	Tail Lift	Column

WARNING LIGHTS ON DASH, GUARD RAILS ON TAIL LIFT INOP


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Dash Warning Lights
Displayed
No Action

2: Fascia Trim
Missing
Replace



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Dented
With Paint Damage




5: Wing nsf
Cracked
Replace




6: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Wing nsf
Scratched
Over 25mm Thru Paint





9: A Post ns
Dented
With Paint Damage



10: Door nsf
Chipped
Multiple Chips



11: Door osf
Chipped
Multiple Chips

12: Door osf
Dented
With Paint Damage



13: Wing osf
Scratched
Over 25mm Thru Paint

14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Moulding of Wing
 Scratched (Painted)
 Up To 25mm Thru Paint

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		Fault	DPF light illuminated		OK
ABS light illuminated		OK			