

VEHICLE INSPECTION REPORT

KM68EJX

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/10/2018

Year 2018

Mileage 118,304 Miles Not Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN WDB9076332P025757

Body Style Panel Van L2

MOT Due 11/01/2027

CAP Clean £8,650.00

CAP Average £7,325.00

CAP Below £5,575.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH EUROTEK TYRE CHANGER, EUROTEK WHEEL BALANCER, HONDA AIR COMPRESSOR, AD BLUE, SIDE LOADING DOOR

Tyres

NSF

NSR

OSF



OSR

Spare

Features


- Front electric windows

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Screen Front
Chipped
UpTo 10mm



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Dented
Between 10mm + 30mm

6: Door nsf
Dented
Over 30mm



7: Fuel Flap
Dented
With Paint Damage

8: B Post ns
Dented
Between 10mm + 30mm



9: Door nsr
Scratched
Over 25mm Thru Paint

10: Door nsr
Dented
Between 10mm + 30mm



11: Qtr Panel nsr
Dented
Over 30mm

12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

14: Reflector nsr
Missing
Replace



15: Door nsr
Scratched
UpTo 25mm Thru Paint



16: Door nsr
Dented
Between 10mm + 30mm



17: Door osr
Scratched
Over 25mm Thru Paint




18: Door nsr
Dented
Between 10mm + 30mm



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Qtr Panel osr
Scratched
Over 25mm Thru Paint





21: Lamp osr
Broken
Replace

22: B Post os
Scratched
Over 25mm Thru Paint



23: Door osf
Dented
With Paint Damage

24: Switches And Controls
Broken
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	Fault			Oil warning light illuminated	OK		
Airbag light illuminated	Fault			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		