

VEHICLE INSPECTION REPORT

NU18HUA

Man TGX 18.420

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 17/04/2018

Colour BLUE

Gearbox AUTOMATIC

Year 2018

VIN WMA06XZZXJM786265

Axle Combi 4x2

Mileage 691,307 Km Warranted

Body Style Tractor Unit

Rear Suspension Air

Fuel Type DIESEL

MOT Due 30/04/2027

GVW 28000kg

Cab Type XLX CAB

INTERMITTENT GEAR SELECTION SLIDING 5TH WHEEL

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos




1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Dented
With Paint Damage

6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

8: Qtr Panel osr
Dented
Over 30mm



9: Qtr Panel osr
Dented
Over 30mm

10: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



11: Door osf
Dented
With Paint Damage

12: Door Moulding osf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		