

VEHICLE INSPECTION REPORT

DX20UKS

Daf LF 180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 02/07/2020

Year 2020

Mileage 452,200 Km Not Warranted

Fuel Type DIESEL

GVW 7500kg

Colour GREEN

VIN XLRAEL1500L495249

Body Style Box Van

MOT Due 31/07/2027

Cab Type SLEEPER CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Air

Rear Doors Barn

GLASS FRAILS

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Cruise control
- Central locking
- Park assist camera
- Cloth seat trim
- Radio/CD
- Front electric windows

Photos





Condition Check



Damage Photos



1: Panel Front
Cracked
Replace

2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Cracked
Replace

4: Bumper Front
Dented
With Paint Damage



5: Door Mirror Assy nsf
Broken
Replace

6: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Door osf
Scratched
Over 25mm Thru Paint



9: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

10: Door Pad osf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		