

VEHICLE INSPECTION REPORT

FL70VBJ

DAF CF 320

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 07/12/2020

Year 2020

Mileage 259,624 Km Not Warranted

Fuel Type DIESEL

GVW 26000kg

Colour GREEN

VIN XLRASM4700G307201

Body Style Refuse Collector

MOT Due 31/01/2027

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Rear Suspension Steel

HILLEND PK21 BODY, TERBERG SINGLE BIN LIFT

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3




OSO4

Features

- Cruise control
- Air conditioning
- Cloth seat trim


Photos








Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Wing osf
Scratched
Over 25mm Thru Paint



5: Door osf
Dented
Over 30mm

6: Qtr Panel osr
Rusted
Over 5mm



7: Wing nsf
Scratched
Over 25mm Thru Paint

8: Door nsf
Dented
Over 30mm



9: Door Moulding osf
Scuffed (Unpainted)
Over 100mm

10: Qtr Panel nsr
Rusted
Over 5mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average	Odour	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK