

VEHICLE INSPECTION REPORT

VU15RMY

Scania R 520 V8

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/04/2015

Year 2015

Mileage 1,301,200 Km Not Warranted

Fuel Type DIESEL

GVW 44000kg

Colour GREEN

VIN YS2R6X20005374608

Body Style Tractor Unit

MOT Due 31/07/2026

Cab Type TOPLINE CAB

Gearbox MANUAL

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WARNING LIGHTS ON DASH SLIDING 5TH WHEEL


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Leather seat trim


Photos







Condition Check



Damage Photos



1: Wing of
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Bumper Front
Chipped
Multiple Chips



5: Bumper Front Moulding
Broken
Replace

6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint

8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Door nsf
Scratched
Over 25mm Thru Paint

10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint

12: Qtr Panel nsr
Cracked
Replace



13: Qtr Panel osr
Cracked
Replace

14: Qtr Panel osr
Scratched
Rusted



15: Door osf
Chipped
Edge Chip

16: Door osf
Scratched
Over 25mm Thru Paint



17: Seat Base Cover osf
Holed
Over 3mm

18: In Car Entertainment
Missing
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK