

VEHICLE INSPECTION REPORT

PE63NSU

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 04/12/2013

Year 2013

Mileage 651,029 Km Not Warranted

Fuel Type DIESEL

GVW 7500kg

Colour RED

VIN XLRAE45FF0L433038

Body Style Box Van

Service history Yes

Service documents Printout

MOT Due 31/05/2027

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Tail Lift Cantilever

WARNING LIGHT ON DASH

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm

2: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Cracked
Replace

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing osf
Scratched
Over 25mm Thru Paint

6: Door osf
Dented
With Paint Damage



7: Qtr Panel osr
Rusted
Over 5mm

8: Tailgate
Rusted
Over 5mm



9: Qtr Panel nsr
Rusted
Over 5mm



10: Door nsf
Dented
With Paint Damage



11: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	Fault		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK