

VEHICLE INSPECTION REPORT

PO13ECW

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/04/2013

VIN XLRAE45FF0L425372

Gearbox MANUAL

Year 2013

Body Style Box Van

Axle Combi 4x2

Mileage 294,813 Km Warranted

Service history Yes

Rear Suspension Steel

Fuel Type DIESEL

Service documents Printout

Tail Lift Cantilever

GVW 7500kg

MOT Due 31/12/2026

Colour RED

Cab Type DAY CAB

WARNING LIGHT ON DASH

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Carpets Front
Torn
Over 10mm

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Rusted
Over 5mm

4: Wing osf
Cracked
Replace



5: Door osf
Dented
Over 30mm

6: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel osr
Rusted
Over 5mm

8: Tailgate
Rusted
Over 5mm



9: Qtr Panel nsf
Rusted
Over 5mm

10: Door nsf
Dented
With Paint Damage



11: Wing nsf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK