

VEHICLE INSPECTION REPORT

LN16NXV

Daf LF 220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 03/03/2016

Year 2016

Mileage 386,663 Km Not Warranted

Fuel Type DIESEL

GVW 18000kg

Colour WHITE

VIN XLRAEL3700L450199

Body Style Skiploader

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

WARNING LIGHTS ON DASH HYVALIFT NG2012XL GEAR (YEAR 2015), SHEETING SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4


Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing of
Cracked
Replace



2: Bonnet
Scratched
Up To 25mm Thru Paint



3: Number Plate Front
Broken
Replace

4: Bumper Front
Rusted
Over 5mm



5: Bumper Front
Dented
Between 10mm + 30mm

6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Dented
With Paint Damage

8: Door nsf
Dented
With Paint Damage



9: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm

12: Qtr Panel osr
Dented
With Paint Damage



13: Door osf
Chipped
Edge Chip

14: Door Mirror Assy osf
Broken
Replace



15: A Post os
Scratched
UpTo 25mm Thru Paint

16: Seat Base Cover osf
Holed
Over 3mm



17: Switches And Controls
Broken
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	Fault		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	Fault		Service indicator light illuminated	OK