

VEHICLE INSPECTION REPORT

FN70AZO

Daf Trucks CF CF 320

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 07/12/2020

VIN XLRASM4700G307007

Gearbox AUTO

Year 2020

Body Style Refuse Collector

Axle Combi 6x2

Mileage 222,010 Km Not Warranted

Body Builder HILLEND

Steering Combi Rear-Lift Steer

Fuel Type DIESEL

Keys 1

Rear Suspension Air

Colour GREEN

Cab Type DAY CAB

HILLEND PLK21-1M BODY, TERBERG BIN LIFT

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Air conditioning
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm



2: Door of
Dented
With Paint Damage



3: Bonnet
Chipped
1 To 5

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel osr
Rusted
Over 5mm

6: Door nsf
Dented
With Paint Damage



7: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

8: Qtr Panel nsr
Rusted
Over 5mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition			Odour		
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK