

VEHICLE INSPECTION REPORT

BX09FZO

Daf LF 45.180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 24/08/2009

Year 2009

Mileage 207,322 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAE45FF0L352854

Body Style Box Van

Keys 2

Service history Yes

Service documents Electronic / Online

Cab Type DAY CAB

Gearbox auto

Doors 2

Steering Combi Steer

Rear Suspension Steel

Rear Doors Roller

Tail Lift Column

* NO POWER STEERING *

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4

Features

- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos







Plate		DTP Ref. No.	
BX09 FZU		006428	
Vehicle Identification No. XLR4E45F0L352854			
Model DAF /FA 4510 H184			
Year of Original Registration 24/08/09			
Year of Manufacture 2009			
Speed Limit N			
Description of Weights Applicable to vehicle			
Gross Weight 10000 10000			
Train Weight 13500 13500			
Gross Weight 13500 13500			
Train Weight 13500 13500			
Date of issue			
DEPARTMENT FOR TRANSPORT GREAT BRITAIN			



Vehicle registration number	
BX09 FZU	
Description TAIL LIFT TEST	
This equipment was Thoroughly Examined on 12/9/2023	
Signed by	S. Rennie
Printed name	S. RENNIE
THE THOROUGH EXAMINATION REPORT FOR THIS EQUIPMENT EXPIRES ON THE DATE SHOWN BELOW:	
11/3/2024	
THE EQUIPMENT MUST NOT BE USED AFTER THIS DATE.	
A copy of the full Examination report can be obtained by:	
Telephone: 0870 8204328 Option 2	



Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm



2: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



3: Carpets Front
Torn
Over 10mm



4: Bonnet
Chipped
1 To 5



5: Bumper Front
Dented
With Paint Damage



6: Wing osf
Cracked
Replace



7: Door osf
Dented
Over 30mm



8: Qtr Panel osr
Rusted
Over 5mm



9: Tailgate
Rusted
Over 5mm



10: Qtr Panel nsr
Rusted
Over 5mm



11: B Post ns
Rusted
Over 5mm



12: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

Fault