

VEHICLE INSPECTION REPORT

NU18GKF

Man TGX 18.420

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 24/04/2018

Colour BLUE

Gearbox AUTOMATIC

Year 2018

VIN WMA06XZZ0JM787294

Axle Combi 4x2

Mileage 607,025 Km Warranted

Body Style Tractor Unit

Rear Suspension Air

Fuel Type DIESEL

MOT Due 31/08/2026

GVW 28000kg

Cab Type XL CAB

SLIDING 5TH WHEEL

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Scratched
Over 25mm Thru Paint



3: Panel Front
Scratched
Over 25mm Thru Paint

4: Bumper Front
Dented
Over 30mm



5: Door nsf
Dented
Over 30mm

6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel Moulding ns
Scuffed (Unpainted)
UpTo 100mm

8: Qtr Panel Trim ns
Broken
Replace



9: Qtr Panel Moulding os
Broken
Replace

10: Qtr Panel osr
Dented
Over 30mm



11: Wing osf
Scratched
Over 25mm Thru Paint

12: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



13: Door osf
Dented
With Paint Damage

14: Door Pad osf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		